

**CERTIFICATE REGARDING SAFE DRINKING WATER AND
SANITARY CONDITION CERTIFICATE**

No.- 77

Date- 12/2/2021

It is certificate that an inspection team headed by Rajesh Tiwari, Assistant Engineer, P.H.E., G.W.R. Sub-Dn. Jagdalpur of P.H.E., G.W.R. Sub-Dn. Jagdalpur inspected D.A.V. MUKHYAMANTRI PUBLIC SCHOOL LALAGUDA, BLOCK BASTANAR DISTT. BASTAR (C.G.) on 15.12.2020 and found that D.A.V. MUKHYAMANTRI PUBLIC SCHOOL LALAGUDA, BLOCK BASTANAR DISTT. BASTAR (C.G.) has safe drinking water facilities for student and members of staff is maintaining hygienic sanitation condition in the school and the campus as per the norms prescribed by the Central/State/Union Territory Government.

Expire on - 15.12.2021

Signature with Seal :

Assistant Engineer
Public Health Engg.
Ground Water Recharge Sub-Dn.
JAGDALPUR (C.G.)

Name :

Designation :

To

Principal,

*D.A.V. MUKHYAMANTRI PUBLIC
SCHOOL LALAGUDA, BLOCK
BASTANAR DISTT. BASTAR (C.G.)*

(Name and Address of the Institution)